

## Introduction: Volkswagen Diesel 1.9 and 2.0 TDi with PD (Pumpe Düse)



Coverage of TDI Training Seminar 2010:

- 1998 thru 2004 TDI ALH Series.
- 2005 and newer PD (Pumpe Düse).
- Overview with the BEW BHW BKW (Pumpe Düse) systems.
- Data Block Diagnostics Interpretation.
- Basic settings, readiness monitors and adaptations.
- > TDI system theory and principles.
- > Field expertise, generation overview and shortcuts to diagnostics.
- Live Diagnostic Data Blocks
- 400+ page Diagnostic manual included with Seminar

This seminar will introduce and aid the shop owner – technician to understand and maintain all Volkswagen diesel engines from the AHU, IZ, ALH to the new PD engines. In this training session, all aspects of diagnostics, repair and maintenance will be at your finger tips.

VW and Audi training with technical support Call 1-866-245-7602 Email:esatinc@esatinc.ca

This seminar is designed to offer field experience and a training manual that will help solve maintenance issues, diagnosis and drivability problems.

Included are diagnostic component testing, adjustments and adaptations for all Volkswagen passenger vehicles like the Golf, Jetta and Passat.

With this seminar, timing belt and start of injection adjustments are illustrated with tooling and specifications using a VAG style scan tool.



The first goal of this seminar is to instruct and train the modern day technician to service and repair the VW diesel engines with confidence and eliminate costly come backs.

The second goal is to increase customer retention with tested knowledge and competent diagnostic skills.

The third goal is to prepare the modern technician for the new, clean and quite diesel production engines coming to North America.



Live diagnostics includes:

- Start of injection adjustments
- MAF monitoring and defect analysis
- Turbo charger testing
- Cold start starting analysis
- > Glow plug monitoring and adjustments
- > EGR testing and adaptations
- > Data block interpretations
- Using the VAG style scan tool

Feel free to visit the ESAT Inc web site and join the technicians forum.


http://www.esatinc.ca

"there are no answers, it's the choices that are made" AF

VW and Audi training with technical support Call 1-866-245-7602 Email:esatinc@esatinc.ca

This seminar will help guide the technician and shop owner on better decisions for parts purchases during routine service. The following example is the engine mount bolt replacement when ever the mount is replaced.

Failure to replace these bolts will cause the rear engine web to break and the engine will drop.



Inteperpreting data correctly will aid in those mysterious lack of power complaints.

Display group 000 (decimal displayed value)												
	Engine idling											
Rea	ad n	neas	surii	ng v	alue	e blo						
х	Χ	X	Х	Х	Х	Х	Χ	Χ	Χ			
1	2	3	4	5	6	7	8	9	10	<b>◀</b> Display fields	Specification	Corresponds to
										Mass air flow	69 to 117	230 to 390 mg/H
									Fue	l temperature	91 to 201	20° to 80°C
								Int	ake	air temperature	182 to 50	10° to 100°C
							Eng	ine	coo	ant temperature	80 to 35	80° to 110°C
						Bar	ome	tric	pre	ssure	Not relevant	-
					Ма	nifol	d ab	sol	ute p	ressure	Not relevant	-
				Inje	ctio	n qu	antit	У			15 to 45	3 to 9 mg/stroke
Accele						pe	dal p	osi	tion		0	0 %
Start of injection 0 to 88								0 to 88	3° ATDC to			
									4° BTDC			
	Engine speed										37 to 43	780 to 903 RPM





Secure Payment options.



Sam	inar	Date:

**Host Facility:** 

VW and Audi training with technical support Call 1-866-245-7602 Email:esatinc@esatinc.ca