



Announcement for the Porsche Cayenne


For those shop owners and technicians that are interested in expanding the repair and maintenance model line, the Porsche Cayenne will now be included in diagnostics services with technical support.

The system is different to handle but not difficult. A dongle will be required to access the systems. Included is a complete scan of a 2006 Cayenne with the V6 engine. As of this posting, special labels are being created to fit another version of VCDS. Included are two images of the cluster and comfort control. The last portion indicates the autoscan for this particular system.

The screenshot shows the VCDS software interface. At the top, it displays 'Comm Status' with 'IC=1 TE=0 RE=0' and 'Protocol: KWP2000'. The main title is 'VCDS Open Controller'. Below this is the 'Controller Info' section, which includes fields for 'VAG Number: 7L5 920 970 G', 'Component: KOMBIINSTRUMENT RB8 3710', 'Soft. Coding: 0015204', and 'Shop #: Imp: 000 WSC 128452'. There are also 'Extra:' fields, one of which contains 'Geraet 00000'. The interface is divided into two main functional areas: 'Basic Functions' (labeled 'These are "Safe"') and 'Advanced Functions' (labeled 'Refer to Service Manual !'). The 'Basic Functions' area contains buttons for 'Fault Codes - 02', 'Readiness - 15', 'Meas. Blocks - 08', 'Advanced ID - 1A', 'Supp. Codes - 18', and 'Adv. Meas. Values'. The 'Advanced Functions' area contains buttons for 'Coding II - 11', 'Coding - 07', 'Basic Settings - 04', 'Adaptation - 10', 'Output Tests - 03', and 'Security Access - 16'. At the bottom center, there is a button labeled 'Close Controller, Go Back - 06'.

Further advancement will follow with more news. The advancement will include adaptations, readiness with recoding. The Immobilizer will also be included in this model. Refer to the Kessy documents that were published earlier this year.

VW and Audi training with technical support
Call 1-866-245-7602 Email: esatinc@esatinc.ca

Comm Status IC=1 TE=0 RE=0 Protocol: KWP2000 /		 VCDS Open Controller	
Controller Info			
VAG Number:	7L0 959 933 F	Component:	37 HSG 0300
Soft. Coding:	0001045	Shop #:	Imp: 552 WSC 05732
Extra:	Tuersteuergeraet FS 0201 7L0959702G Tuersteuergeraet BF 0201 7L0959703C Tuersteuergeraet HL 0201 7L0959704C Tuerst		
Extra:	7L0907719A Neigungssensor 0020 7L5951171 Innenraumsensor 0020		
Basic Functions These are "Safe"		Advanced Functions Refer to Service Manual !	
Fault Codes - 02	Readiness - 15	Coding II - 11	Coding - 07
Meas. Blocks - 08	Advanced ID - 1A	Basic Settings - 04	Adaptation - 10
Supp. Codes - 18	Adv. Meas. Values	Output Tests - 03	Security Access - 16
Close Controller, Go Back - 06			

VCDS Version: Beta 9PA (Sorry Uwe but I just had to)
 Data version: 2009 (Available)

Friday,31,July,2009,15:22:27:10531

VIN: WP1AA29P26LAXXXXX

 Address 01: Engine

Part No SW: 6SL VAS N60 000 HW: 022 906 032 GF
 Component: 0041700034HESLVAG 0148
 Coding: 0000133
 Shop #: WSC 128452 000 00000

No fault code found.
 Readiness: 0000 0000

 Address 02: Auto Trans

Part No: 09D 927 750 DL
 Component: AL 750 6A 0858
 Coding: 0012328
 Shop #: WSC 128452 000 00000

No fault code found.

VW and Audi training with technical support
Call 1-866-245-7602 Email: esatinc@esatinc.ca

Address 03: ABS Brakes
Part No: 7L0 907 379 G
Component: ESP ALLRAD MK25 0203
Coding: 0021510
Shop #: WSC 128452 000 00000

No fault code found.

Address 05: Acc/Start Auth.
Part No SW: 3D0 909 139 A HW: 5WK 484 96
Component: Kessy 6700
Revision: 67005715 Serial number: VWZ3Z0EXXXXXXX
Coding: 0524449
Shop #: WSC 31414 000 00000

Part No: XXXXXXXXXXXX
Component: ELV XXXX

No fault code found.

Address 08: Auto HVAC
Part No: 7L5 907 040 AR
Component: Klima - SG R/L 4021
Coding: 0000030
Shop #: WSC 128452 000 00000

No fault code found.

Address 09: Cent. Elect.
Part No: 7L5 937 049 D
Component: 3002
Coding: 0102398
Shop #: WSC 31414 000 00000

No fault code found.

VW and Audi training with technical support
Call 1-866-245-7602 Email: esatinc@esatinc.ca

Address 15: Airbags

Part No: 3D0 909 601 H
Component: 25 Airbag 8.4E++H01 0573
Revision: BB38727 Serial number: 0005605:
Coding: 0012853
Shop #: WSC 128452 000 00000

Part No: 659 256 .50 .0
Component: BF-Gewichtsens.

No fault code found.

Address 16: Steering wheel

Part No: 7L5 953 549 D
Component: Lenksäulenmodul 1701
Coding: 0001311
Shop #: WSC 31414 000 00000

No fault code found.

Address 17: Instruments

Part No: 7L5 920 970 G
Component: KOMBIINSTRUMENT RB8 3710
Coding: 0015204
Shop #: WSC 128452 000 00000

No fault code found.

Address 19: CAN Gateway

Part No: 7L5 907 530 A
Component: Gateway CAN/CAN E1 1200
Revision: ateway C Serial number: yyyyyyyyyyy

No fault code found.

Address 22: AWD Labels: None

Part No: 0AD 927 755 AM
Component: TRANSFERCASE 1110
Shop #: WSC 00000 000 00000

No fault code found.

VW and Audi training with technical support
Call 1-866-245-7602 Email: esatinc@esatinc.ca

Address 46: Central Conv.
Part No: 7L0 959 933 F
Component: 37 HSG 0300
Coding: 0001045
Shop #: WSC 05732 552 00000
Protocol: 53

Part No: 7L0 959 701 G
Component: Tuersteuergeraet FS 0201

Part No: 7L0 959 702 G
Component: Tuersteuergeraet BF 0201

Part No: 7L0 959 703 C
Component: Tuersteuergeraet HL 0201

Part No: 7L0 959 704 C
Component: Tuersteuergeraet HR 0201

Part No: 7L0 907 719 A
Component: Neigungssensor 0020

Part No: 7L5 951 171
Component: Innenraumsensor 0020

No fault code found.

Address 56: Radio

No Faults Found
or DTCs not supported by controller
or a communication error occurred

End -----

Access to technical support and training for this system is available through
Euro Systems Automotive Training Inc.

“There are no answers, it’s the choices that are made” Augie Ferron

VW and Audi training with technical support
Call 1-866-245-7602 Email: esatinc@esatinc.ca