

Posted by: Larry Sheldrick
Larry's Performance Werks Inc.
815 Merrimon Avenue
Asheville, NC 28804-2404

These are a few screen captures of the coolant temp sensor on a 2005 TDI Jetta I repaired today using the Ease software.



Just thought you might be interested.

This defective sensor was indeed the ominous "black" outdated sensor which I replaced with a "green". It is very important to know NOT to use sensors from Luxembourg, they have given us a ton of problems.

We presently use only sensors made in Spain from FAE. Check out the temp reading when the drop occurred.



© Larry Sheldrick
Larry's Performance Werks Inc.
815 Merrimon Avenue
Asheville, NC 28804-2404



© Larry Sheldrick
Larry's Performance Werks Inc.
815 Merrimon Avenue
Asheville, NC 28804-2404